



Command= 210-

Point#, Start#-End# or G#= 1-100

Bearing	Distance	Elev	Descrip	Pnt.	Northing	Easting	Type
-----09-23-2023-----15:59:40-----D:\BENCH FILES\BM10							
	50.00		SETHUB	1	4885.7290	4720.9493	
	68.85		SETHUB	2	5044.7590	4903.0010	TRA
	41.74		FNDIPIN	3	4828.5957	4634.7792	SS
	46.44		CLTRNCH	4	4874.7886	4644.2355	SS
	50.70		CLTRNCH	5	4939.5672	4694.0368	SS
	47.39		EDGLAWN	6	4866.6794	4685.0505	SS
	46.63		EDGLAWN	7	4840.0426	4741.1918	SS
	47.11		EDGLAWN	8	4811.4930	4786.7042	SS
	49.53		EDGLAWN	9	4779.9671	4837.6839	SS
	56.16		8'TOWL	10	4761.8386	4900.0441	SS
	55.17		GND	11	4830.5449	4867.6001	SS
	67.00		TOPWELL	12	4877.0394	4929.3382	SS
	64.02		CORDECK	13	4901.0160	4894.2865	SS
	62.77		CORDCK**	14	4905.2743	4860.7395	SS
	62.76		CORDCK**	15	4923.1989	4839.1211	SS
	58.72		@POOL	16	4903.9107	4840.8789	SS
	56.35		BSEDGLN	17	4902.4103	4833.6919	SS
	57.47		CORDECK	18	4927.6701	4833.7440	SS
	61.36		TS@DCK	19	4942.1588	4844.6237	SS
	62.70		DK@GAR	20	4951.0719	4852.8401	SS
	63.15		CORGAR	21	4962.8713	4838.5686	SS
	59.67		TOPTANK?	22	4966.2823	4829.3825	SS
	61.08		COVER**	23	4966.0603	4830.2305	SS
	60.83		FILTCAP	24	4967.5049	4828.0863	SS
	57.30		BS	25	4973.6248	4815.0558	SS
	53.81		CORSHED	26	4959.9167	4790.1614	SS
	53.51		CORSHED	27	4951.0879	4781.5053	SS
	53.34		CORSHED	28	4962.4199	4769.8596	SS
	53.06		BMBAR**	29	4921.6276	4739.3066	SS
	54.41		PIT#1	30	4939.3931	4802.1603	SS
	50.73		PIT#2	31	4900.8418	4754.9958	SS
	50.49		TS	32	4904.3362	4715.8624	SS
	50.01		GND	33	4869.2440	4769.7291	SS
	50.48		GND	34	4846.8726	4799.6162	SS
	51.61		GND	35	4822.2984	4831.5052	SS
	54.52		GND	36	4850.0830	4851.0234	SS
	54.39		GND	37	4881.5241	4827.3662	SS
	53.35		GND	38	4902.4350	4798.0297	SS
	55.83		BS	39	4939.7257	4817.9191	SS
	53.65		ENDBS	40	4989.2675	4768.7975	SS
	53.26		CLTRCH	41	5008.7228	4751.8660	SS
	66.35		FNDIP	42	5111.1454	4865.4312	SS
	66.07		POLE	43	5111.4518	4862.3409	SS
	70.75		POLE#47	44	5080.8819	4916.8595	SS
	76.30		IP*****	45	4991.9186	4997.4554	SS
	71.92		CLDREP5*	46	5062.1891	4938.0458	SS

JOB #12 315DAOUST [100]

Bearing	Distance	Elev	Descrip	Pnt.	Northing	Easting	Type
-----09-23-2023-----15:59:40-----D:\BENCH FILES\BM10							
		66.25	CLDR**	47	5012.0050	4894.9877	SS
		63.29	CORGAR	48	4982.9529	4855.5179	SS
		66.45	CORBLD**	49	4969.9617	4875.6534	SS
		66.72	CORBLD	50	4957.8191	4894.6505	SS
		67.58	CORHSE	51	4929.5251	4917.8759	SS
		65.99	ENDRET??	52	5005.0866	4899.4621	SS
		61.70	TRIPBRCH	53	5028.3879	4851.0599	SS
		57.04	GND	54	5001.7604	4815.2719	SS
				55	5111.3497	4865.5933	TRA
				60	5000.0000	5000.0000	
				61	4977.2440	4991.5334	TRA
				62	4840.6613	4940.7161	TRA
				63	4632.1319	4870.6057	TRA
				64	4828.5957	4634.7792	TRA
				65	5134.5898	4884.5643	TRA

Point#, Start#-End# or G#= 4-

Map 23 lot 13

50  
68.85

1996 system  
replaced

hse built 1976

purchased 1983


~~RISER~~ RISER (THINKS 2')  
OVER TANK

Well

IF BOOKER ??  
Now ??

NO FNUA  
DRAINS

WATER  
12 1/2  
12 1/2  
2 1/2  
Rusted



would  
like to  
leave  
in place

design for 4

Wells  
on other  
sided of river  
land is privately  
owned

50' R.O.W.  
next to Miller  
VWD EREC  
2 8" water lines

KNOW ALL MEN BY THESE PRESENTS, That Constance P. Nihan, formerly known as Constance P. Luce, of North Hampton, County of Rockingham, and State of New Hampshire

for consideration paid, grant to Paul N. Daoust and Kathleen E. Daoust of Swanzev, County of Cheshire, and State of New Hampshire as joint tenants with rights of survivorship

with warranty covenants the following described premises:

A certain tract or parcel of land located on the southerly side of Winnicut Road in the Town of North Hampton, County of Rockingham and State of New Hampshire and being bounded and described as follows:

Beginning at an iron pin on the southerly side of Winnicut Road at an iron pin at the northeasterly corner of the within described premises; thence proceeding S 20-34-30 W along land now or formerly of Booker and Cornelius 24.28' to a drill hole in a stone wall; thence continuing S 20-34-30 W along said stone wall and Booker and Cornelius land 145.73' to drill a hole in said wall; thence turning and proceeding S 18-35-00 W along said stone wall and Booker and Cornelius land 220.00' to an iron pin; thence turning and running N 50-12-10 W along other land now or formerly of Lora A. and Jean E. Booker 306.94' to an iron pin; thence turning and running N 39-13-30 E along other land now or formerly of said Bookers 395.00' to an iron pin set at southerly side of Winnicut Road; thence turning and running S 50-25-00 E along said Winnicut Road to the point of beginning.

For title reference see deed to said Bookers dated October 22, 1947 and recorded in the Rockingham County Registry of Deeds, Book 1088, Page 16.

Being the same premises conveyed to Constance P. Luce by Dennis R. Luce dated November 19, 1979 and recorded in the Rockingham County Registry of Deeds at Book 2354, Page 0932, meaning and intending to convey lot #4 on plan entitled "Subdivision of land of Laura A. Booker in North Hampton, New Hampshire, scale 1"=50', May, 1976, Parker Survey Associates, Inc., Seabrook, N.H."

38 72 90  
34 13-30  
10-21-31  
28 51 41

106716



Steven D. Nihan, husband ~~wife~~ of said grantor, release to said grantee S all rights of homestead and other interests therein.

Witness, their hands and seals this 18th day of April, 1983

Witness  
to book

Constance P. Nihan L.S.

Steven D. Nihan L.S.

L.S.

State of New Hampshire

Rockingham

ss.:

April 18, A.D. 1983

09882




APR 18 9 21 AM '83



SUBDIVISION OF LAND  
OF  
**LORA A. BOOKER**  
IN  
**NORTH HAMPTON, N.H.**  
SCALE: 1" = 50' MAY 1976  
PARKER SURVEY ASSOC. INC.  
SEABROOK, N.H.



Approved By  
North Hampton Planning Board  
Date 4 Aug 1976  
*Walter S. Leime*  
Chairman



**C-6170**

2080



State of New Hampshire  
DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095  
(603) 271-3501 FAX (603) 271-6683



June 11, 2001

STOCKTON SERVICES  
PO BOX 1306  
HAMPTON NH 03842

RE: WN: 200103247, Paul Daoust, Map/Lot: 23 / 13, North Hampton


Dear Designer:

A review of the information you provided for this proposed disposal system has been completed. We regret to inform you that this plan is disapproved at this time. However, if the following items are addressed, we will reconsider the application:

1. Is the well radius located entirely within the lot lines? If not please provide a copy of the recorded well release or easement.
2. Please provide the previous construction approval number or provide all inverts.

If you have any questions, please respond to me at the address above.

Sincerely,

  
Jocelyn S. Degler  
Subsurface Systems Bureau  
Water Division

cc: Designer File # 00348

- # 1 HOUSE WAS BUILT IN THE MID 1970's.  
EXISTING WELL PREDATES 1989  
RULES AND IS GRANDFATHERED
- # 2 PREVIOUS APPROVAL NUMBER  
FROM YOUR OFFICE BASED ON  
AVAILABLE INFO - 33422.



# APPROVAL FOR CONSTRUCTION

N.H. DEPARTMENT OF ENVIRONMENTAL SERVICES  
SUBSURFACE SYSTEMS BUREAU  
CA2001035569 P.O. BOX 95, 6 HAZEN DRIVE, CONCORD, NH 03302-0095 APPROVAL NO. CA2001035569

THE PLANS AND SPECIFICATIONS FOR SEWAGE OR WASTE DISPOSAL SYSTEM SUBMITTED FOR:

OWNER:

PAUL DAoust  
76 WINNICUT RD  
NORTH HAMPTON NH 03862-  
Map No./Lot No.: 23 / 13  
Subd. Appvl. No. 10391  
Subd. Name: LAURA A BOOKER  
County: ROCKINGHAM  
Registry Book No.: 2441  
Registry Page No.: 0120  
Probate Docket No.:  
(If Applicable)

COPY SENT TO:

BUILDING INSPECTOR  
PO BOX 710  
NORTH HAMPTON NH 03862  
Type of System: 3 BR  
450 GPD  
Town/City Location: NORTH HAMPTON

BY APPLICANT: PERMIT NO.

Street Location 76 WINNICUT ROAD

Subsurface waste disposal systems must be operated and maintained in a manner so as to prevent nuisance or health hazard due to system failure.  
(RSA 485-A:37)  
It is unlawful to discharge any hazardous chemicals or substances into subsurface waste disposal systems. Included are paints, thinners, gasoline and chlorinated hydrocarbon solvents such as TCE, sometimes used to clean failed septic systems and auto parts.  
(Env-Ws 410.05)

STOCKTON SERVICES  
PO BOX 1306  
HAMPTON NH 03842

ADVISE YOUR CONTRACTOR OF REQUIRED CHANGES  
IN PLANS AS INDICATED BELOW CONDITIONS

Approved this date:

Date amended:

07/11/2001

By: JOCELYN S DEGLER

N.H. Department of Environmental Services Staff

Revised 6/97

200103247

APPLICANT'S

# PERC TEST DATA

CA 2001 035569

REVIEWED AND APPROVED  
IN ACCORDANCE WITH THE  
REQUIREMENTS OF THE  
NH DEPT OF ENVIRONMENTAL SERVICES  
WATER DIVISION  
PERC RATE:  
DESIGN LOADING:  
AREA REQUIRED:  
AREA PROPOSED:

5/7/01  
6 min/in DEPTH: 24"  
3 BEDROOMS  
675 SF  
25 x 30 = 750 SF

## PROPOSED REPLACEMENT SEPTIC SYSTEM PLAN

LOCUS: 76 WINNICUT ROAD  
NORTH HAMPTON, NH  
OWNER: PAUL DAoust  
76 WINNICUT ROAD  
NORTH HAMPTON, NH 03862

APPLICANT:  
STOCKTON SERVICES  
PO BOX 1306  
HAMPTON, NH 03842

DATE: 5/28/01

APPROVAL:

315

DESIGNER  
OF  
SEPTIC SYSTEMS  
W. W. Belding  
No. 348

APPROVED  
Town of North Hampton  
Septic System Examiner  
Michael Cemo

RECEIVED  
JUN 04 2001